



CESARONI
TECHNOLOGY
INCORPORATED

Cesaroni Technology Incorporated
1144 Tallevast Road
Suite 108
Sarasota, FL 34243
Telephone: 941-360-3100
Fax: 941-360-3188

Cesaroni Technology Incorporated
2561 Stouffville Road
PO Box 246
Gormley, ON L0H 1G0
Telephone: 905-887-2370
Fax: 905-887-2375

23 August, 2011

Subject: AeroPack minimum diameter retainers for Pro38™ and Pro54™

Dear Pro38/Pro54 user,

This letter is to inform you that CTI approves the use of AeroPack minimum diameter motor retainers for use with Pro38™ and Pro54™ reloads.

Usage of the AeroPack minimum diameter motor retainers will not affect the performance of the reload and/or void warranty, provided that the motor ejection charge is first completely removed as per Pro38™/Pro54™ instructions.

Please note the following:

- The complete ejection charge should be removed – including the blackpowder charge that is present in the flash-hole in the forward closure.
- The minimum diameter retainers should be used for motor retention only. They are not suitable for recovery system retention.

We wish you many great flights to new records using these minimum diameter retainers.

Regards,

Cesaroni Technology Inc.
Jeroen Louwers